

**Inspection Photos**  
**Location Name: Dunbar #1**  
**API: 05-123-23247**



**Photo 1: Location, looking SE**



**Photo 2: Wellhead, looking E**

**Inspection Photos**  
**Location Name: Dunbar #1**  
**API: 05-123-23247**



**Photo from prior inspection for comparison**



**Photo from operator**



**Inspection Photos**  
**Location Name: Dunbar #1**  
**API: 05-123-23247**



**Photo from prior inspection for comparison**



**Photo from operator**

**Inspection Photos**  
**Location Name: Dunbar #1**  
**API: 05-123-23247**



**Photo from prior inspection for comparison**



**Photo from operator**






**Inspection Photos**  
**Location Name: Dunbar #1**  
**API: 05-123-23247**



**Photo from prior inspection for comparison**




**Photo from operator**

**Inspection Photos**  
**Location Name: Dunbar #1**  
**API: 05-123-23247**



**Photo from prior inspection for comparison**



**Photo from operator**