

Inspection Photos

01/02/2018

Operator: DENVER EAST MACHINERY COMPANY
- 24040

Location ID: 390528

Inspection Doc. Number: 682503018
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 1: Photo taken from the southeast end of the location, facing northwest.



Photo 2: Photo taken from the east end of the location, facing west. Photo show additional rock armoring has been used to repair the degradation within the stormwater berm.

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 3: Photo taken from the northeast end of the location, facing northeast. Photo shows that the silt fence appears to have been repaired, however areas of the fence already appear to be in disrepair. Advise maintenance before further damage.



Photo 4: Photo taken from the north end of the location, facing west. Photo show additional rock armoring has been used to repair the degradation within the stormwater berm.

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 5: Photo taken from the northwest end of the location, facing southwest. Photo shows straw wattle BMPs have been repaired.



Photo 6: Photo taken from the west end of the location, facing northeast.



Photo 7: Photo taken from the southwest area of the disturbance, and the well location, facing northeast. Inspection #682501119 and inspection #682502721 identified and documented this debris and required its removal. Refer to photos 9-11 in inspection 682501119 and photo 23 in inspection #682502721. Photo shows debris has not been removed per the corrective action.




Photo 8: Photo from inspection #682502721 (#23) dated 10/18/2017.



Photo 9: Photo taken from the south end of the location, facing north. Photo shows maintenance appears to have been conducted at the berm BMP.



Photo 9:



Photo 10: