

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2018

Submitted Date:

01/04/2018

Document Number:

689300596

**FIELD INSPECTION FORM**

Loc ID 306335 Inspector Name: O'Donnell, Shaun On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10311  
Name of Operator: SRC ENERGY INC  
Address: 1675 BROADWAY SUITE 2600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, Dave		dpennington@srcenergy.com	
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287931	WELL	PR	05/11/2010	GW	123-24463	LOWE 31-14	PA

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Wells have been PA, battery has been removed. Gas meter run and pig launcher are still on location. Gas meter run is still connected, unsure if line was capped under ground where separator used to be. See attached photos		
Corrective Action:	Comply with Rule 603.f . For unused, unmarked flowline risers 24 hrs to lock out tag out, 30 days to remove riser.	Date:	02/04/2018

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Pig Station	# 1		
Comment:	40.43968, -104.83016		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	40.43968, -104.83016		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 287931 Type: WELL API Number: 123-24463 Status: PR Insp. Status: PA

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Wells have been PA, battery has been removed. Gas meter run and pig launcher are still in place. Gas meter run is still connected upstream and downstream. Upstream riser possibly burried and capped	odonnells	01/04/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300597	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4341294">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4341294</a>