

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/28/2017

Submitted Date:

12/29/2017

Document Number:

685100309**FIELD INSPECTION FORM**

Loc ID 424085	Inspector Name: NEIDEL, KRIS	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 4 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:

OGCC Operator Number: 10525

Name of Operator: SANTA FE NATURAL RESOURCES INC

Address: 4833 FRONT STREET UNIT B 506

City: CASTLE ROCK State: CO Zip: 80104

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccenforcement@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	
SULLIVAN, MICHAEL	(303) 681-5901	durangopl@earthlink.net	
		dnr_cogccengineering@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424081	WELL	SI	09/01/2016	OW	081-07664	STATE 41-14-1	EI

General Comment:

On 12/28/2017 COGCC Environmental staff inspected the State 41-14-1. Weather was 34 degs and clear, snow covered the ground. Free oil was observed inside the flare pit, wildlife fencing around flare pit was in disrepair. The oil in the pit appears to be (circular) 5 ft in radius by 1ft. The volume was estimated to be greater than 5 bbl's. As a result an eForm 19 should be submitted within 72 hrs (as of 12/29/2017). Gauge hatches on all three above ground tanks were open, hatches should be closed within 24hrs (per COGCC corrective action matrix). It was observed that the gas drive on the pumping unit was running, the well was NOT pumping. Operator response to these items is required immediately.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Pit	
Comment:	Gas being vented or flared during non-upset condition without prior approval from COGCC. Fluid (oil) present in flare pit.	
Corrective Action:	Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.	Date: 01/05/2018

Inspected Facilities									
Facility ID:	424081	Type:	WELL	API Number:	081-07664	Status:	SI	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: FlareLined: NOPit ID: Lat: 40.472732Long: -107.578150Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment:

a Form 15, Pit Permit has not been filed with the COGCC for this pit.

Corrective Action

The operator should submit a From 15 for the pit on this location.

Date: 01/08/2018c**Fencing:**Fencing Type: WildlifeFencing Condition: InadequateComment:

fence is in disrepair

Corrective Action

repair fence

Date: 01/05/2018**Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401500135	photo	state well.pdf
401500731	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4339301
685100310	photo	state well.pdf