

Final Reclamation Inspection

January 3, 2018

Operator: ANADARKO E&P ONSHORE LLC - 2800

API: 05-123-31811

Weld County, CO

NESW Section 1 T8N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HOBART #8-67-1-11
API: 05-123-31811



Google Earth imagery taken on October 14, 2017 illustrating the access road that has not been reclaimed per Rule 1004 standards- refer to Photo 6 . Well location appears to meet Rule 1004 standards- refer to Photos 1-4.

Inspection Photos
Location Name: HOBART #8-67-1-11
API: 05-123-31811



Photo 1. Photo taken from the approximate center of location, facing West. Well location appears reflective of reference area vegetative levels.



Photo 2. Photo taken from the approximate center of location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: HOBART #8-67-1-11
API: 05-123-31811



Photo 3. Photo taken from the approximate center of location, facing East. See comments under Photo 1.



Photo 4. Photo taken from the approximate center of location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: HOBART #8-67-1-11
API: 05-123-31811



Photo 5. Reference photo taken northwest of the location, facing North. See comments under Photo 1.



Photo 6. Photo taken from a portion of the access road, facing West. Gravel remains on access road and access road has not been contoured to match the surrounding landscape per Rule 1004 standards.