

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 2. Vegetation, annual, and noxious weeds on and in berm.



Photo 3. Gauge hatch on 300 bbl tank in foreground is open.

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



**Photo 4. 7 frack tanks each with fluid in them.
Stored on location with no secondary
containment.**



**Photo 5. Equipment stored on location. Rills coming
onto location.**

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 6. Equipment stored on location.



Photo 7. Equipment stored on location.

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 8. Stained soil at wellhead.



Photo 9. Close-up of stained soil at wellhead.

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 10. Rathole covered with wooden slats with fluid present.



Photo 11. Close-up of rathole fluid.

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 12. Debris on location.



Photo 13. Debris on location.