

Photo#1:
View of Entry into Location; some Debris remains.



December 20, 2017

Photo#2:

Overview of Location to Northwest; Vegetation is not yet to the 80% of Reference Requirement.



December 20, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Standard Shale API#045-06913

Photo#3:

What appears to be Stockpiled Soil at SW Corner (edge) of Location was not incorporated into recontouring of Site.

Photo#4:

