

# Inspection Photos

01/02/2018

Operator: LEGADO DJ, LLC - 200039

Location ID: 388436

Inspection Doc. Number: 682503022

Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: LEGADO DJ, LLC - 200039  
Location ID: 388436



**Photo 1:** Photo taken from the west end of the location, facing north. Photo shows large area of the location that have not achieved uniform, desirable perennial vegetative cover, and remains predominantly exposed soil.



**Photo 2:** Photo taken from the west end of the location. Photo shows areas of the location where vegetation has not established, and remain predominantly exposed soil.

Inspection Photos  
Operator: LEGADO DJ, LLC - 200039  
Location ID: 388436



**Photo 3:** Photo taken from the southwest corner of what appears to have been the former pit location, facing north. Photo shows areas of the pit where vegetation has failed to establish. Remediation may be required due to potential salinity concerns.



**Photo 4:** Photo taken from the northwest corner of what appears to have been the former pit location, facing east. Photo shows areas of the pit where vegetation has failed to establish. Remediation may be required due to potential salinity concerns.

Inspection Photos  
Operator: LEGADO DJ, LLC - 200039  
Location ID: 388436



**Photo 5:** Photo taken from the northwest corner of what appears to have been the former pit location, facing south. Photo shows areas of the pit where vegetation has failed to establish. Remediation may be required due to potential salinity concerns.



**Photo 6:** Photo taken from the south end of the location, facing north.

Inspection Photos  
Operator: LEGADO DJ, LLC - 200039  
Location ID: 388436



**Photo 7:** Photo taken from the southern end of the location, facing north. Location does not meet reclamation standards. Photo shows large areas of the location that have not achieved uniform, desirable perennial vegetative standards, and remains predominantly exposed soil.



**Photo 8:** Photo taken from the southern end of the location, facing east. Location does not meet reclamation standards. Photo shows large areas of the location that have not achieved uniform, desirable perennial vegetative standards, and remains predominantly exposed soil.

Inspection Photos  
Operator: LEGADO DJ, LLC - 200039  
Location ID: 388436



**Photo 9:** Photo taken from the western end of the location, facing east. See comments under photo 7



**Photo 10:** Photo taken from the northwestern end of the location, facing south. See comments under photo 7



**Photo 11:** Photo taken from the eastern end of the location, facing west. See comments under photo 7



**Photo 12:** Photo taken from the adjacent reference area. Vegetation observed appears to be predominantly a Blue grama / Buffalo grass mix.