

Interim Reclamation and Stormwater Inspection

January 9, 2018

Operator: NEWPEK LLC - #10484

Location ID: 445039

Inspection Document #: 682403196

Weld County, CO

NWSW Section 20 T9N R56W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Fauver /1-20
Location ID: 445039



Photo 1. Photo taken from the entrance of the location off CR 102, facing South.



Photo 2. Photo taken from the western location, facing North. Operator has installed surface roughening BMP around the perimeter of the location which should be used in conjunction with other stormwater BMPs. Portions of the surface roughening BMP are in need of maintenance.

Inspection Photos
Location Name: Fauver /1-20
Location ID: 445039



Photo 3. Photo taken from the northwest location, facing East. See comments under Photo 2.



Photo 4. Photo taken from the northern location, facing East. See comments under Photo 3. Equipment traffic has damaged the BMP.

Inspection Photos
Location Name: Fauver /1-20
Location ID: 445039



Photo 5. Photo taken from the northeast location, facing South. Appears the Operator has salvaged and stored topsoil along the eastern location. Topsoil has been temporarily stabilized with hydromulch.



Photo 6. Photo taken from the southeast location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: Fauver /1-20
Location ID: 445039



Photo 7. Photo taken from the southern location, facing West. See comments under Photo 4.



Photo 8. Photo taken from the southwestern location, facing West. See comments under Photo 4.