

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2018

Submitted Date:

01/05/2018

Document Number:

674902014**FIELD INSPECTION FORM**Loc ID 378716 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 69805Name of Operator: PETROX RESOURCES INCAddress: P O BOX 2600City: MEEKER State: CO Zip: 81641**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Nystrom, Dusty	505-330-1328	nystrow@yahoo.com	<a href="#">All Inspections</a>
Clark, Mike	970-878-5594	mike.petroxcbm@gmail.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
St John, William (Cal)		cal.stjohn@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301884	WELL	PR	07/01/2013	GW	007-06275	LARK 33-5 21-2	EI
444385	WELL	PR	12/01/2016	LO	007-06323	Lark 33-5 21-4	EI

**General Comment:**

On January 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Petrox Resources Inc. Lark 33-5 #21-4. This field inspection resulted from a complaint regarding a release on the location. For the most recent field inspection report of this facility, please refer to document #674901232.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing sign located near each well head.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact number used to attempt to notify operator of release at separator. Number listed on location signs, 970-878-5595, has been disconnected. Petrox representative used a marker to temporarily correct the signs on this location during this inspection. Actual operator contact phone number is 970-878-5594.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 02/05/2018
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Produced Water	WELLHEAD		
Comment:	COGCC staff notified of release near well head 1/4/18. Horizontal tank, attached to the well, had been removed by the time of this inspection.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.		Date: 02/05/2018
Produced Water	Separator		
Comment:	Hammer union on water line observed dripping during this inspection. Ice and fluids within separator housing. Petrox representative notified of release. Connection was tightened up, and release was stopped.		
Corrective Action:	Securely fasten all valves , pipes, and fitting to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 01/06/2018
In Containment: No			
Comment:			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Vertical Heated Separator	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	301884	Type:	WELL	API Number:	007-06275	Status:	PR	Insp. Status:	EI
Facility ID:	444385	Type:	WELL	API Number:	007-06323	Status:	PR	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On January 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Petrox Resources Inc. Lark 33-5 #21-4. This field inspection resulted from a complaint regarding a release on the location. Imaged submitted to the COGCC showed a horizontal tank attached to the well head with fluids around it and mist coming from the top of the tank. For the most recent field inspection report of this facility, please refer to document #674901232.</p> <p>The horizontal tank had been removed, reportedly earlier on 1/5/18, by the time of this field inspection. A mark from the skid was present where the tank sat. Damp soil was present surrounding the area where the tank was located. Dusty Nystrom, Petrox representative, collected a soil sample of the impacted area. 5 - 4 oz. glass sample jars and two Ziploc bags were filled with the damp soil from 37.08489/-107.40588 for analysis at Green Analytical Laboratory.</p> <p>The contact information on the well signs was temporarily corrected with a marker, when the operator was told that the listed number had been disconnected.</p> <p>During this inspection a leaking hammer union in the separator shack for the #21-4 was observed. The operator was notified and the connection was tightened up, stopping the release.</p>	hughesj	01/05/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401505000	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4342573">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4342573</a>
674902015	Inspection Photos 1/5/18	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4342566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4342566</a>