

Well Name : Herrera 5

API # : 067-06776



Photo 1: Wellhead sign.



Photo 2: Pump jack, electric panel, and wellhead..

Well Name : Herrera 5

API # : 067-06776



Photo 3: Wellhead flowlines right side.



Photo 4: Wellhead flowlines left side.



Well Name : Herrera 5

API # : 067-06776



Photo 5: 1" steel riser with pump jack in background.



Photo 6: 3" steel lines on edge of slope with pump jack in background.

Well Name : Herrera 5

API # : 067-06776



Photo 7: 3" steel lines heading down slope.



Photo 8: Erosion channels on E side of location.



Well Name : Herrera 5

API # : 067-06776



Photo 9: Power pole and power panel for electric motor on pump jack.



Photo 10: Erosion channel on W side of location.

Well Name : Herrera 5

API # : 067-06776



Photo 11: Impacted soil on W perimeter of location.



Photo 12: Impacted soil on W perimeter of location with pump jack in background.



Well Name : Herrera 5

API # : 067-06776



Photo 13: Close up of impacted soil.



Photo 14: Wood debris on location.

Well Name : Herrera 5

API # : 067-06776



Photo 15: Disconnected power line at wellhead.



Photo 16: Tank at remote battery location (Herrera 3).