

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2018

Submitted Date:

01/10/2018

Document Number:

689500484**FIELD INSPECTION FORM**Loc ID 316391 Inspector Name: GRANAHAN, KYLE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone        | Email                            | Comment                      |
|------------------|--------------|----------------------------------|------------------------------|
| Allred, Josh     | 970-629-5914 | jallred@foundationenergy.com     | <a href="#">Rangely area</a> |
| Contact, General |              | regulatory@foundationenergy.com  | <a href="#">Regulatory</a>   |
| ,                |              | dnr_cogccengineering@state.co.us |                              |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 272001      | WELL | SI     | 02/01/2017  | GW         | 103-10433 | COLUMBINE SP FED 3C-13-4-104 | SI          |

**General Comment:**[On location to conduct routine inspection.](#)

**Location**Overall Good: ☒

|                      |                                                                           |       |            |
|----------------------|---------------------------------------------------------------------------|-------|------------|
| <b>Signs/Marker:</b> |                                                                           |       |            |
| Type                 | BATTERY                                                                   |       |            |
| Comment:             | Located at entrance of location – Missing nearest access road field wide. |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.b.                                   | Date: | 03/11/2018 |
| Type                 | WELLHEAD                                                                  |       |            |
| Comment:             | Present/complete                                                          |       |            |
| Corrective Action:   |                                                                           | Date: |            |

**Emergency Contact Number:**

Comment: 866-767-3600

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                                   |       |            |
|--------------------|-----------------------------------|-------|------------|
| Type               | UNUSED EQUIPMENT                  |       |            |
| Comment:           | Sucker rod and tubing on location |       |            |
| Corrective Action: | Comply with Rule 603.f .          | Date: | 04/18/2018 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                                   |                 |       |                 |
|-----------------------------------|-----------------|-------|-----------------|
| <b>Equipment:</b>                 |                 |       | corrective date |
| Type: Horizontal Heated Separator | # 1             |       |                 |
| Comment:                          |                 |       |                 |
| Corrective Action:                |                 | Date: |                 |
| Type: Deadman # & Marked          | # 4             |       |                 |
| Comment:                          |                 |       |                 |
| Corrective Action:                |                 | Date: |                 |
| Type: Bird Protectors             | # 1             |       |                 |
| Comment:                          |                 |       |                 |
| Corrective Action:                |                 | Date: |                 |
| Type: Gas Meter Run               | # 1             |       |                 |
| Comment:                          |                 |       |                 |
| Corrective Action:                |                 | Date: |                 |
| Type: Pump Jack                   | # 1             |       |                 |
| Comment:                          | CBM rotary pump |       |                 |
| Corrective Action:                |                 | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 272001 Type: WELL API Number: 103-10433 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITE

Comment: SI - no leaks/venting . No current MIT on record or delinquent as required by Rule 326  
Production records indicate well last produced in August 2014.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan.Date: 01/20/2018

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            |                         |                       |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |

Comment: No sediment flow evident

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: YES

Pit ID:

Lat:

Long:

Reference Point: SE

Other: \_\_\_\_\_

Length: 8Width: 8**Lining:**Liner Type: OtherLiner Condition: AdequateComment: fiberglass

Corrective Action

Date: g**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL                                                                                                                                                                 |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401510043    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4346808">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4346808</a> |
| 689500493    | photo lof            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4346797">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4346797</a> |