

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2018

Submitted Date:

01/16/2018

Document Number:

690100308**FIELD INSPECTION FORM**
 Loc ID 327249 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246590	WELL	TA	09/01/2017	GW	123-14387	NAAB-USX UU 3-4	EG

General Comment:

COGCC Inspector met with the Anadarko contractor (A&W Water/ Hydro Excavation Services) on location. Details of observations made during this field inspection are available in the flowline section of this report. Photos uploaded can be accessed via link(s) at end of report.

Inspected Facilities

Facility ID: 246590 Type: WELL API Number: 123-14387 Status: TA Insp. Status: EG

Flowline

#1	Type:	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Size:	Material:	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
<u>Comment:</u>	This well has been plugged and abandoned; Form 6 doc #401288894 filed with COGCC on 05/22/2017; Form 42 field operations notice doc #401394285 filed on 09/05/2017. There are (2) hydro excavation crews currently working on the excavation/ removal of flowlines associated with this well; including well site flowline (wellhead to facility) and dump lines at facility (previously shared facility with KP Kauffman).		
<u>Corrective Action:</u>			<u>Date:</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100317	Signage at facility	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352789
690100318	Crew working to expose/ remove Anadarko flowlines	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352790
690100319	Wellsite flowline removal (view West from PA well)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352791