

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/02/2018

Submitted Date:

01/12/2018

Document Number:

689800729

FIELD INSPECTION FORM

Loc ID 312938 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10407
Name of Operator: ANTLER ENERGY LLC
Address: PO BOX 104
City: BAGGS State: WY Zip: 82321

Findings:

- 10 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Evans, Clay		antlerenergy@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222936	WELL	PR	04/24/2015	GW	081-06298	ROSS-GOVERNMENT-USA 43-7	SI

General Comment:

Routine FIU follow-up inspection.
Follow up to inspection from 12/2/2016 document number 673403906. All corrective actions remain outstanding.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers. No tank labels on green tanks. Labels on tank tanks peeling.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	02/12/2018
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	307-380-7616	Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Horizontal Heated Separator	# 2		
Comment:	40.92579, -108.32790		
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Bird Protectors	#		
Comment:	No wildlife protection apparent on tank tanks exhaust.		
Corrective Action:	Install wildlife screen per Rule 605.b.(7).	Date:	02/12/2018

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	Open Top			
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate			Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		40.925610,-108.328090	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate			Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLs	HEATED STEEL AST		40.925900,-108.327960	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		

Earth	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 222936 Type: WELL API Number: 081-06298 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: _____ Lat: 40.925880 Long: -108.327670

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: No pit permit on file.

Corrective Action

Date: 07/18/2016

COGCC Comments

Comment	User	Date
<u>Follow up to inspection from 12/2/2016 document number 673403906. All corrective actions remain outstanding.</u>	waldrone	01/12/2018
<u>Landfarm with stained soil at 40.92615, -108.32785 bermed. Please work with COGCC environmental, Kris Neidel kris.neidel@state.co.us 970-871-1963, to ensure proper management and disposal of materials.</u>	waldrone	01/12/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401512599	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4349579
689800752	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4349565