

Inspection Photos  
Location Name: HL 11-89-19 1  
Location ID: 422990



**Photo 1. Top soil has been placed on cut slope to mitigate erosion. Site will need to be reevaluated in the future. Tanks have been removed from location.**



**Photo 2. Equipment and trash on location.**