

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/17/2018

Submitted Date:

01/22/2018

Document Number:

685304200

FIELD INSPECTION FORM

Loc ID 326584 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 24 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	
Trujillo, Etta		ettrujillo@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258298	WELL	PR	05/07/2001	GW	067-08350	ALLISON UNIT 147	PR

General Comment:

[Inspection completed as routine inspection requirement.](#)

[This inspection does not alleviate requirement to open corrective actions from previous inspections.](#)

[See link at end of report for path to downloadable pictures.](#)

Location			
Lease Road:			
Type	Access		
comment:	Dirt two track access road.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal sign mounted on tank battery fencing.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Production tanks do not have NFPA label on tank or fencing. Similiar issue noted in previous inspection document number 674601114.		
Corrective Action:	Install required labels to comply with Rulke 210.d.	Date:	03/24/2018
Type	CONTAINERS		
Comment:	Label directly on tank.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Identified (1) unused flowline/riser on E side of separator. Flowline risers not LO/TO or marked are considered unused equipment.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Impacted soil around base of wellhead. Less than a 5 gallon bucket clean up.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Steel post and pole with livestock fencing panels.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Steel post and hog wire fencing.		
Corrective Action:		Date:	

Type	PUMP JACK		
Comment:	Safety rails.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Lube oil tank.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas motor.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:	In use - 4" steel flowline from wellhead casing to separator inlet. All points co-located. In use - 2" steel flowline from wellhead tubing to separator inlet. All points co-located. In use - 4" steel flowline from separator outlet to gas meter inlet. All points co-located. In use - 1" steel supply gas line from Separator outlet to wellhead. All points co-located. In use - 1" steel supply gas line from separator outlet to tank battery. All points co-located. Unused - 1" steel riser with valve and plug at E end of separator. (B) point unknown.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Located (4) anchors. Similiar issue noted in previous inspection document number 674601114.		
Corrective Action:	Locate and remove or mark deadmen to comply with Rule 1003.a.	Date:	02/22/2018
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:	Tanks (2) and Separator (1).		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	500 BBLs	HEATED STEEL AST		
Comment: Above ground heated 500 BBL tank with earthen berms.					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	500 BBLs	HEATED STEEL AST		
Comment: Disconnected above ground heated 500 BBL steel tank. Tank is located inside bermed area with in use 500 BBL produced water tank.					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 258298 Type: WELL API Number: 067-08350 Status: PR Insp. Status: PR

Producing Well

Comment: [Review of electronic well file indicates last reported production was Sep 2017.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Location constructed on top of ridge with cut and fill slopes. Vegetation consist of Juniper pine, Pinion pines, Sage Brush, and mixed grasses.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTRURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment

Corrective Action

Date _____

Guy line anchors marked? Fail

Comment Located (4) anchors. Similiar issue noted in previous inspection document number 674601114.

Corrective Action Locate and remove or mark deadmen to comply with Rule 1003.a.

Date 02/22/2018

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Fail	

Comment: [Lube oil day tank with no spill prevention.](#)

Corrective Action: [Install or repair required BMPs to comply with Rule 1002.f.](#)

Date: 02/22/2018

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304217	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4358138