

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2018

Submitted Date:

01/12/2018

Document Number:

679700794**FIELD INSPECTION FORM**Loc ID 419243 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLCAddress: 730 17TH ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Miller, Meagan	832-746-8446	mmiller@bayswater.us	
Barbula, Don	303-912-4213	dbarbula@bayswater.us	
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	All PDC inspection

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425992	TANK BATTERY	AC	09/08/2010		-	MOJACK TANK BATTERY	EI

General Comment:

COGCC Environmental Inspection of aging unresolved spill #2523635. Correction actions from Inspection 673803588 have also been completed. However compressor walls have collapsed again. See comments below. Form 10 Change of Operator submitted on 01/08/2018 and in process.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	Truck Loadout	<= 1 bbl		
Comment:	Spill present at produced water tanks loadout at 28-C Battery. See photo.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. and handle oily waste in accordance with Rule 907.e.			Date: 02/11/2018

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Compressor walls fallen on ground		
Corrective Action:	Repair and secure compressor walls to prevent continued maintenance issue		
		Date:	02/11/2018

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**

Comment: [Spill #2523635](#) stated that crude oil tank at the Mojack 1-28 overflowed within secondary containment berm at the Mojack 1-28,2-28 tank battery. It appears that oily waste was removed or properly remediated. Operator submitted analytical results to COGCC. The Mojack 28-C Pad tank battery was constructed after this spill. [Spill #2523635](#) is resolved.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401516396	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352816
679700795	Inspection Photos 1-12-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352722