

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2018

Submitted Date:

01/17/2018

Document Number:

688600218

FIELD INSPECTION FORM

Loc ID 428669 Inspector Name: BURGER, CRAIG On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 1
Name of Operator: UNKNOWN
Address: _____
City: _____ State: _____ Zip: _____

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425793	WELL	TA	10/12/2011	LO	077-40017	Lloyd and Lowell 1	TA

General Comment:

Orphan well plugging project. Contractor is RACS.

Inspected Facilities

Facility ID: 425793 Type: WELL API Number: 077-40017 Status: TA Insp. Status: TA

Workover

Comment: 8 am on location. Slickline tagged at 286'. Ran camera, liquid at ~60', gas bubbling. RIH tubing and circulated calcium water at 10.5 ppg. Lost backside, some flow. Dug pit for flow and pumped water to tank. Pumped 80 sacks cement at ~280'. Well static. Off location 12:30.

Corrective Action: **Plug and abandon.**

Date: 01/31/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401517613	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4353799