

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/18/2018

Submitted Date:

01/19/2018

Document Number:

689400869

FIELD INSPECTION FORM

Loc ID 324466 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 77330
Name of Operator: SG INTERESTS I LTD
Address: 100 WAUGH DR SUITE 400
City: HOUSTON State: TX Zip: 77007

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
All Inspections,		inspection@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211720	WELL	PR	06/12/2012	GW	051-06042	JACOBS 29-1	PR

General Comment:

This is a follow up inspection to FIR Doc#680200091. Any corrective actions not addressed from previous inspections are still applicable.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Produced water signs have been updated.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Posted Emergency Contact Number 1-866-261-9766	
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds appear to have been removed. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: _____				
Corrective Action: _____				Date: _____

Venting:

Yes/No	NO		
Comment: _____			
Corrective Action: _____			Date: _____

Flaring:

Type		
Comment: _____		
Corrective Action: _____		Date: _____

Inspected Facilities

Facility ID: 211720 Type: WELL API Number: 051-06042 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Could not do complete stormwater inspection due to snow cover. Chemical is still present in chemical containment at the well head. No cover is in place over containment, and is open to wildlife. Original corrective action date is still applicable.

Corrective Action: Remove chemicals in containment and cover containment to prevent entry by wildlife.

Date: 11/10/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401520474	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4356199
689400870	Jacobs 29-1 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4356193