

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2018

Submitted Date:

01/29/2018

Document Number:

690100336**FIELD INSPECTION FORM**
 Loc ID 318197 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240857	WELL	SI	11/01/2017	OW	123-08645	CHAMPLIN 41-4 1	EG

General Comment:

COGCC Inspector met with the Anadarko contractor (Nail Services) on location. Details of observations made during this field inspection are available in the flowline section of this report. Photos uploaded can be accessed via link(s) at end of report.

Inspected FacilitiesFacility ID: 240857 Type: WELL API Number: 123-08645 Status: SI Insp. Status: EG**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type:	Size:	Material:
Variance:	Age:	Contents:

Integrity Summary

Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:

Pressure Testing

Witnessed:	Test Result:	Charted:
------------	--------------	----------

COGCC Rules(check all that apply)
☐ 1101. Installation and Reclamation
 ☐ 1102. Operations, Maintenance, and Repair
 ☒ 1103. Abandonment

Comment: This well has been plugged and abandoned; Form 6 doc #401327818 filed with COGCC on 06/29/2017; Form 42 notice of start of plugging operations doc #401409284 filed on 09/20/2017. Contract roustabout crews are currently working on the excavation/ removal of flowlines at the associated facility/ battery; this facility is in the process of being decommissioned and services additional wells with the following API numbers: 123-22119, 123-16503, 123-08861, 123-08646. Production equipment is being removed at the facility. Flowlines in the process of removal include wellhead, dump and process pipe flowlines.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100346	Signage and view of project site (to South)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363456
690100347	Flowlines removed at battery (view North)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363457
690100348	Flowlines removed from location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363458