

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2018

Submitted Date:

01/29/2018

Document Number:

685304250**FIELD INSPECTION FORM**Loc ID 311970 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Redmond, Nolan	720-484-2347	Inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280224	WELL	PR	10/23/2012	GW	067-09074	IGE 107	PR
297563	WELL	DG	12/01/2017	LO	067-09615	IGE 132	PR

General Comment:

Inspection completed as follow-up inspection to verify completion of corrective actions from previous inspection document number 685304069. Inspection report contains additional corrective action. See Good Housekeeping section for additional details.

This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.

See link at end of report for path to downloadable pictures.

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Framed metal sign located at gas meter run.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Fracturing sand pile left on location after well completion. Corrective action was not completed. Corrective action date remains the same to document days of non-compliance.		
Corrective Action:	Take actions to control fugitive dust per Rule 805.c.	Date:	12/19/2017
Type	UNUSED EQUIPMENT		
Comment:	High pressure hose at wellhead.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.	Date:	03/01/2018
Type	DEBRIS		
Comment:	Pipe thread protectors at separator.		
Corrective Action:	Remove debris to comply with Rule 603.f.	Date:	03/01/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Wellhead.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
-----------------	--	--	--

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 280224 Type: WELL API Number: 067-09074 Status: PR Insp. Status: PRFacility ID: 297563 Type: WELL API Number: 067-09615 Status: DG Insp. Status: PR**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304265	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363814