

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/26/2018

Submitted Date:

01/30/2018

Document Number:

690100340

**FIELD INSPECTION FORM**

Loc ID 320793 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10110  
 Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
 Address: 1801 BROADWAY #500  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
DONATO, SCOTT	(303) 398-0537	SDONATO@GWOGCO.COM	
Sherman, Susan		susan.sherman@state.co.us	
Chesson, Bob		robert.chesson@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
	(303) 398-0537	cogccinspections@gwogco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204960	WELL	SI	08/01/2015	GW	005-07095	KRAUS-ALBIN 22-20	EG

**General Comment:**

Engineering Integrity Inspection performed on January 26th, 2018 in response to initial form 19 spill report Doc #401524345 received by COGCC on 01/25/2018 that outlines: Soil impacts were discovered during removal of the separator and associated flowlines. Details of observations made during this field inspection are available in the equipment, housekeeping and flowline sections of this report. This field inspection also serves as a followup to FIR Doc #688300925 performed on 01/02/2018. Photos uploaded can be accessed via link(s) at end of report.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type: UNUSED EQUIPMENT

Comment: [Action Required Completed from FIR Doc #688300925; Tank battery/ equipment has been removed from location.](#)

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Bird Protectors

# 0

corrective date

Comment: [Action Required Completed from FIR Doc #688300925; Tank battery/ equipment has been removed from location.](#)

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 204960 Type: WELL API Number: 005-07095 Status: SI Insp. Status: EG

**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: Yes Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: This well has been plugged and abandoned; form 6 doc #401361941 filed with COGCC on 08/01/2017 and form 42 start of plugging operations notice doc #401395607 received on 09/06/2017. The production equipment/ tanks at facility have been removed. The wellhead flowline has been abandoned in place (or removed). The dump flowlines and process piping on location have been removed (Action Required Completed from FIR Doc #688300925). There were no flowline risers identified on or around location. Excavation and remediation activities in response to historical release are in progress.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>1103. ABANDONMENT</b>                      Each pipeline abandoned in place shall be disconnected from all sources and supplies of natural gas and petroleum, purged of liquid hydrocarbons, depleted to atmospheric pressure, and cut off three (3) feet below ground surface, or the depth of the pipeline, whichever is less and sealed at the ends. This requirement shall also apply to compressor or gas plant feeder pipelines upon decommissioning or closure of a portion or all of a compressor station or gas plant.</p> <p>*Also Note: For flowlines abandoned/ Notice of such abandonment shall be filed with the Commission (via eform 42) and with the local governmental designee or local government jurisdiction.</p>	maclarej	01/30/2018
<p>The Actions Required outlined on COGCC Field Inspection Doc #688300925 performed on 01/02/2018 by Susan Sherman have been completed.</p>	maclarej	01/30/2018
<p>Note: There is a disconnected/ out of service gas gathering riser and meter run on the North end of location.</p>	maclarej	01/30/2018
<p>COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.</p>		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100352	View of location (looking South)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4364728">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4364728</a>
690100353	Flowlines removed/ misc trash in container	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4364729">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4364729</a>
690100354	View from PA wellhead to facility (looking West)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4364730">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4364730</a>
690100355	Gas gathering riser and unused meter run	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4364731">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4364731</a>