

Photo#1:
Overview of Location from NE corner to SW.



January 19, 2018

Photo#2:

Unused Equipment on Location

Photo#3:



January 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


Inspection Photos: Caerus Schideler Loc#431050

Photo#4:

Ditches & slopes have remnants of large population of senesced non noxious annual weeds that have become Debris.



Photo#5:



January 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Schideler Loc#431050

Photo#6:

Photo#7:

Rill & Chanel Erosion is occurring on Cut Slopes.



January 19, 2018

Photo#8:

Photo#9:

Rill & Chanel Erosion is occurring on Cut Slopes contributing to Sediment Run-on to Location



January 19, 2018

Photo#10:

. Rill & Chanel Erosion is occurring on Cut Slopes contributing to Sediment Run-on to Location



January 19, 2018

Photo#11:

Drain BMP needs maintenance,



January 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Schideler Loc#431050