

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2018

Submitted Date:

01/29/2018

Document Number:

685304252**FIELD INSPECTION FORM**Loc ID 325237 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	<a href="#">All Inspections</a>
Leonard, Mike		mike.leonard@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Weems, Mark		mark.weems@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214374	WELL	SI	07/01/2017	GW	067-05786	UTE B 1	SI

**General Comment:**

Inspection completed as follow-up inspection requirement and verification of compliance with May 2017 Flowline NTO. Previous inspection completed on 06/08/2016 document number 685300628.

This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.

See link at end of report for path to downloadable pictures.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Locked and gated dirt and gravel access road. Access is used a driveway by the landowner and maintained.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Framed metal sign at wellhead fencing.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	The contact number on the wellhead sign (970-867-9388) is not answered. Call rings until message says "Machine is off" and disconnects call. Similiar issue was identified in previous inspection.		
Corrective Action:	Establish a working emergency contact number as required by Rule 210.b.		Date: 03/01/2018
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds inside wellhead fencing identified in the previous inspection requiring corrective action has been completed.		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	Identified (3) risers. See equipment section of report. Flowline risers not LO/TO or marked are considered unused equipment. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		
Corrective Action:	Comply with Rule 603.f.		Date: 03/01/2018
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	6' chainlink cyclone fencing.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Risers S of wellhead - Steel post and pole barriers.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Flow Line	# 2		corrective date
Comment:	37.01547/-107.52533 Unused - 4" steel riser S of wellhead. (B) point unknown. End capped. Unused - 2" steel line S of wellhead. (B) point unknown. Valve bull plugged.		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	37.01554/-107.52525 Unused - 4" steel riser S of wellhead. (B) point unknown. Valve end is not plugged or capped.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:	No audible release or gas detected by Four Gas Monitor.		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 214374 Type: WELL API Number: 067-05786 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI - Status of location does not support reported SI status as all production related equipment has been removed from location and supports TA status. General conditions at location does not appear to of changed since previous inspection. Valves on wellhead are chained off.

Review of electronic well file indicates last reported production as October 2012. Repoting reflects well was in production for 1 day with 0/1 of oil/gas produced. Records indicate the last time the well was in production for more than 1 day was Feb 2000. At that time the well was reported as in production for 26 days producing 59/0 of oil/gas.

Electronic document file indicates Notice of Intent to Abandon was filed 1/2/2018. There are no MIT records in electronic well file to reflect compliance with Rule 326.b.(1).

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan.

Date: 02/09/2018

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Location is area with rural residential properties with Animas River to the E of location and Hwy 550 to the W. The well status has been SI with no activity on location and currently the disturbed area is covered in grass and weedy vegetation. Location appears to be mowed controlling unwanted vegetation. To the S of wellhead appears to be where the production equipment area was located with risers but no other equipment. Large rock and soil pile located along the SE edge of this area.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? PassComment No anchors noted at surface of location.

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401529385	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363819">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363819</a>
685304270	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363816">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363816</a>