

# Inspection Photos

API: 05-067-06549

Operator: CATAMOUNT ENERGY PARTNERS LLC

Inspection Number: 6806024648

Inspection Date: 1/17/2018



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward.**



**Photo 3. View of the northern portion of the project area from northeastern corner facing westward.**



**Photo 4. View of the western portion of the project area from southwestern edge facing northward. Revegetation is progressing but weedy with desirable plans such as Indian ricegrass (*Achnatherum hymenoides*) and rabbitbrush (*Chrysothamnus nauseosus*) as well as weeds such as cheatgrass (*Bromus tectorum*) and alyssum (*Alyssum simplex*).**



**Photo 5. View of erosion occurring where concentrated stormwater flows down the access road creating erosional channels. Stormwater controls are needed.**