

# Construction and Stormwater Inspection

February 7 & 9, 2018

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 451214

Inspection Document #: 682403260

Weld County, CO

NWSE Section 32 T6N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Wake North /32-K  
Location ID: 451214



**Photo 1.** Photo taken from the southern location of the main access road, facing South. Operator has installed a silt fence BMP around the eastern portion of the access road.



**Photo 2.** Photo taken from the southern location perimeter, facing South. Operator has installed a silt fence BMP around the entire perimeter of the location but the silt fence BMP has not been properly installed. A ditch BMP has been installed around the entire perimeter, inside of the silt fence BMP, but has not been installed in accordance with good engineering practices. Appears frozen soil conditions may have resulted in poor installation for both BMPs.

Inspection Photos  
Location Name: Wake North /32-K  
Location ID: 451214



**Photo 3.** Photo taken from the southeast location perimeter on February 7, 2018, facing East. Operator has not properly trenched the silt fence BMP.



**Photo 4.** Photo taken from the southeast location perimeter on February 9, 2018, facing South. See comments under Photo 3.



Inspection Photos  
Location Name: Wake North /32-K  
Location ID: 451214



**Photo 5.** Photo taken from the eastern location perimeter, facing West. Operator has stored topsoil along the southwestern location.

Inspection Photos  
Location Name: Wake North /32-K  
Location ID: 451214



**Photo 6.** Photo taken along a portion of the eastern location on February 7, 2018. See comments under Photo 3.



**Photo 7.** Photo taken along a portion of the eastern location on February 9, 2018. See comments under Photo 3.



Inspection Photos  
Location Name: Wake North /32-K  
Location ID: 451214



**Photo 8.** Photo taken along a portion of the northeastern location. See comments under Photo 3.



**Photo 9.** Photo taken from the northern location perimeter, facing West. See comments under Photo 2.



Inspection Photos  
Location Name: Wake North /32-K  
Location ID: 451214



**Photo 10.** Photo taken from the northern location perimeter, facing West. See comments under Photo 2.



**Photo 11.** Photo taken from the northern location perimeter, facing West. See comments under Photo 2.