

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/09/2018

Submitted Date:

02/13/2018

Document Number:

688000127**FIELD INSPECTION FORM**
 Loc ID 317067 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 14855Name of Operator: CENTRAL OPERATING INCAddress: 1600 BROADWAY STE 1050City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Quintana, Laney	(303) 894-9576	centraloperating@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107552	PIT	AC			-	STATE TANK BATTERY	EI
117543	PIT	AC			-	STATE 4	EI
117703	PIT	AC			-	STATE 1 & 3	EI
235628	WELL	PR	07/19/1968	OW	121-08118	STATE 1	EI

General Comment:

Environmental inspection related to unused oil skim pit. A Form 27 is required for proper oil skim pit closure, see corrective actions.

Inspected FacilitiesFacility ID: 107552 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 117543 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 117703 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 235628 Type: WELL API Number: 121-08118 Status: PR Insp. Status: EI**Producing Well**

Comment: Stuffing box leaking oil. Scattered oily soil in the vicinity of the wellhead (see location photographs), small area of soil subsidence to the southeast of the wellhead in the turnaround.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.
Backfill the area of soil subsidence.

Date: 03/09/2018

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Skimming/SettlingLined: NOPit ID: 117703Lat: 39.752994Long: -103.046798Reference Point: Other: Length: 27Width: 33**Lining:**

Liner Type:

Liner Condition:

Comment:

Former oil skim pit has been bypassed using a skimming tank. The pit appears to be mostly dry and ready to be excavated for closure. An approved Form 27 is required prior to initiation of closure activities.

Corrective Action

Submit an eForm 27 (referencing pit facility ID 117703) to the COGCC for approval.

Date: 02/23/2018c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date: **Netting:**Netting Type: MeshNetting Condition: Holes

Comment:

Remove or repair mesh to prevent wildlife entrapment.

Corrective Action

Date: 02/28/2018

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date: Type: Produced WaterLined: NOPit ID: 117543Lat: 39.753258Long: -103.046652Reference Point: Other: Length: 290Width: 95**Lining:**

Liner Type:

Liner Condition:

Comment:

Two historical pits have been merged into one large pit.

Corrective Action

Date: c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date: **Netting:**

Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:		
Corrective Action		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000128	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377328