

# Inspection Photos

02/09/2018

Operator: PRE RESOURCES INC - 10241

Location ID: 390648

Inspection Doc. Number: 682503133

Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the west end of the location, facing north. Photo shows stormwater and sediment control BMPs (wattles) that have not been maintained, are no longer in proper functioning condition, and is considered debris. Wattle debris was observed on the northern, northwestern and southern ends of the location.



**Photo 2:** Photo taken from the west end of the location, facing northeast. Photo shows additional debris.



**Photo 3:** Photo taken from the west end of the location, facing north. Photo shows additional debris.



**Photo 4:** Photo taken from the west end of the location, facing west. Photo shows areas of the location where vegetation has not achieved a uniform desirable perennial vegetative cover.

Inspection Photos  
Operator: PRE RESOURCES INC - 10241  
Location ID: 390648



**Photo 5:** Photo taken from the west end of the location, facing north. Photo shows areas of the location where vegetation has not achieved a uniform desirable perennial vegetative cover.



**Photo 6:** Photo taken from the west end of the location, facing east. Photo shows areas of the location where vegetation has not achieved a uniform desirable perennial vegetative cover.

Inspection Photos  
Operator: PRE RESOURCES INC - 10241  
Location ID: 390648



**Photo 7:** Photo taken from the west end of the location, facing southeast. Photo shows areas of the location where vegetation has not achieved a uniform desirable perennial vegetative cover.



**Photo 8:** Photo taken from the west end of the location, facing south. Photo shows areas of the location where vegetation has not achieved a uniform desirable perennial vegetative cover.



**Photo 9:** Photo taken from the adjacent reference area. Photo shows vegetation on reference area.



**Photo 10:** Photos 10-15 taken from the access road. Photos shows access road does not meet reclamation standards. Gravel/ruts evident. Road has not achieved a uniform desirable perennial vegetative cover.

Inspection Photos  
Operator: PRE RESOURCES INC - 10241  
Location ID: 390648



Photo 11:



Photo 12:



Photo 13:



Photo 14:



**Photo 15:** Photo taken from the access road. Photo shows gravel remaining.



**Photo 16:** Photo of soils from the adjacent reference area to compare to soils on access road.



**Photo 17:** Most current available aerial imagery (2015). Photo shows ~0.8 miles of access road requiring reclamation.