

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401543999

Date Received:

02/13/2018

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

inspections@catamountep.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 674901962

Inspection Date: 11/09/2017

FIR Submit Date: 11/14/2017

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 311903

Location Name: SEMLER GAS UNIT-N33N8W Number: 16SWSE County: LA PLATA

Qtrqtr: SWSE Sec: 16 Twp: 33N Range: 8W Meridian: N

Latitude: 37.099870 Longitude: -107.719290

### FACILITY - API Number: 05-067-00 Facility ID: 216303

Facility Name: SEMLER GAS UNIT Number: 1

Qtrqtr: SWSE Sec: 16 Twp: 33N Range: 8W Meridian: N

Latitude: 37.099870 Longitude: -107.719290

### CORRECTIVE ACTIONS:

1 ☒ CA# 110631

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.4.

Date: 12/13/2017

Response: CA COMPLETED

Date of Completion: 12/08/2017

Operator Comment: removed stained soil, rerouted exhaust

COGCC Decision: Approved pending re-inspection

Inspection document #674902001 conducted on 12/13/17 observed secondary containment berm repairs. That

|                       |   |
|-----------------------|---|
| COGCC Representative: | inspection document requested analytical results from release #452581 as well as a narrative of activity regarding excavated material present near the well head. Supplemental spill report #401431596 indicates that Envirotech was investigating the release. The operator shall submit these documents, including all analytical results, by 3/1/18. |
|-----------------------|---|

2  CA# 110632

|                    |  |
|--------------------|--|
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC SW EPS. |
|--------------------|--|

Date: 12/13/2017

Response: CA COMPLETED

Date of Completion: 12/08/2017

|                   |  |
|-------------------|--|
| Operator Comment: | removed stained soil, rerouted exhaust |
|-------------------|--|

COGCC Decision: Approved pending re-inspection

|                       |  |
|-----------------------|--|
| COGCC Representative: | During follow up inspection conducted on 12/13/17, inspector observed stained area by muffler exhaust had been addressed. Open excavation and stained soils around well head were observed on this date and a narrative was requested from the operator. The operator shall submit a detailed account of what had taken place regarding this activity by 3/1/18. |
|-----------------------|--|

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed:

Title: Geo/Eng Tech

Date: 2/13/2018 11:32:01 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

|           |                          |
|-----------|--------------------------|
| 401543999 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files