

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	ok		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	rod iron fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:	intermitter controller on wellhead		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:	whole lease SI		
Corrective Action:			Date:

Flaring:			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 281300 Type: WELL API Number: 123-23386 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
High Risk Inspection	montoyaj	02/16/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677400597	Wellhead and Battery Prod Equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4380884