

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2018

Submitted Date:

02/12/2018

Document Number:

685304330**FIELD INSPECTION FORM**
 Loc ID 325536 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 34725Name of Operator: GOSNEY & SONS INCAddress: P O BOX 367City: BAYFIELD State: CO Zip: 81122**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**19 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Barnett, Matt		mattb@gosneyco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214965	WELL	PR	12/03/2012	GW	067-06570	GOSNEY 1	PR

General Comment:

Inspection completed as routine inspection requirement.

This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.

See link at end of report for path to downloadable pictures.

Location				
Lease Road:				
Type	Access			
comment:	Dirt and gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Metal sign at separator.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Operator contact information posted on wellhead sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:	There are sections of abandoned steel lines along the E perimeter of location.			
Corrective Action:	Remove abandoned sections of flowline to comply with Rule 603.f.			Date: 05/14/2018
Type	UNUSED EQUIPMENT			
Comment:	Identified (4) unused risers/flowlines. Flowline risers not LO/TO or marked are considered unused equipment. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.			
Corrective Action:	Comply with Rule 603.f.			Date: 03/15/2018
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Concrete barriers.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Concrete barriers.			
Corrective Action:				Date:
Equipment:				
Type: Flow Line	# 6			corrective date

Comment:	In use - 3" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 3" steel line from separator outlet to gas meter inlet. All points co-located. Unused - 1" steel supply gas line from separator outlet. (B) point unknown. Unused - 1" steel riser on S side of wellhead at surface. It is bent over and marked with concrete cribbing piece on it. (B) points unknown. Riser is open ended, not tagged, plugged, or painted. Unused - 1" steel riser in E perimeter of location. (B) point unknown. Valve is painted and plugged. Unused - 1" steel riser on E side of separator used as part of domestic tap. (B) point unknown. Line is open ended.			Date:
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Domestic tap - Located on SE corner of location. Oderizer equipment, separator, and (3) water cans with valve sets.			Date:
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				Date:
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	Located (4) anchors.			Date:
Corrective Action:				Date:
Type: Other	# 2			
Comment:	Water can and valve set.			Date:
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				Date:
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Telemetry equipment.			Date:
Corrective Action:				Date:
Type: Bird Protectors	# 2			
Comment:	Separator.			Date:
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				Date:
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Wellhead.			Date:
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	Remote tank battery located at Gosney 4-A 067-09507				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	0		OTHER		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	214965	Type:	WELL	API Number:	067-06570	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - Review of electronic well file indicates last reported production a Dec 2017.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Location in operating rock/gravel quarry.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401544929	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377370
685304352	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377310