

Inspection Photos

API: 05-067-05475

Operator: LOGOS OPERATING LLC

Inspection Number: 680602502

Inspection Date: 2/5/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward. Revegetation is progressing with grasses such as blue grama (*Bouteloua gracilis*), smooth brome (*Bromus inermis*), and dropseed (*Sporobolus* sp.).



Photo 3. View of the western portion of the working area from the northwestern corner facing southward.



Photo 4. View of the eastern portion of the project area from the southeastern edge facing northward. Russian thistle and kochia debris from the project area is blowing and gathering on the eastern fence (observed during inspection). This debris needs to be cleaned and properly disposed of.

