

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/21/2018

Submitted Date:

02/22/2018

Document Number:

689100121

FIELD INSPECTION FORM

Loc ID 335544 Inspector Name: LUJAN, CARLOS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 1600 BROADWAY ST STE 2600
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region
Knudson, Dwayne		dknudson@ursaresources.com	Senior Environmental Specialist
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335544	LOCATION	AC			-	NORCROSS-66S93W 13NESW	EI

General Comment:

Environmental inspection conducted in response to spill report doc #401547592. Sunny day. Temp around 40 oF. Snow in the ground. On Site with Dwayne Knudson from URSA. A tank leaked due to a hole at the bottom of the tank. Approx. 110 bbls of fluids leaked and contained in the lined secondary containment. Fluid had been removed. Tank will be decommissioned. No sign of hydrocarbon was observed outside of the secondary containment. URSA inspected the liner and found no evidence of hole or any sign that could indicate a compromised liner. No junk or trash was observed on site. Wellheads and tanks have labels. Tanks have steel lined secondary containment and the pad has a berm on the perimeter.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 335544 Type: LOCATION API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689100122	Tank Battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4384892
689100123	Secondary Containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4384893