

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2018

Submitted Date:

02/22/2018

Document Number:

685304385**FIELD INSPECTION FORM**Loc ID 306790 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 600 E EXCHANGE AVECity: FORTH WORTH State: TX Zip: 76164**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:22 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	SW Inspection Reports
Beaty, Brent	505-330-3210	brent_beaty@xtoenergy.com	SW Inspection Reports
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265094	WELL	PR	08/15/2004	GW	067-08766	ZELLITTI 34-9 34-1	PR
417633	WELL	PR	11/02/2010	GW	067-09817	ZELLITTI 34-9 34-3	PR

General Comment:[Inspection completed as routine inspection requirement.](#)[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)[See link at end of report for path to downloadable pictures.](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:	Labels directly on containers.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Framed metal sign at location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Operator contact information posted on wellhead sign.

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Natural gas motor.		
Corrective Action:		Date:	
Type: Flow Line	# 5		

Comment:	#34-3 In use - 3" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 2" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 1" steel supply gas line from wellhead casing to prime mover knock out pot. All points co-located. In use - 3" steel line from separator outlet to gas meter inlet. All points co-located. In use - 1" steel supply gas line from separator outlet to wellhead. All points co-located.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:	Separators.		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:	Located (6) marked anchors.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Lube oil tank with earthen berm spill prevention.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 5		
Comment:	#34-1 In use - 3" steel line from wellhead casing to separator inlet. All points co-located. In use - 2" steel line from wellhead tubing to separator inlet. All points co-located. In use - 3" steel line from separator outlet to gas meter inlet. All points co-located. In use - 1" steel supply gas line from wellhead casing to prime mover knock out. All points co-located. In use - 1" steel supply gas line from separator outlet to wellhead. All points co-located.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 265094 Type: WELL API Number: 067-08766 Status: PR Insp. Status: PR**Producing Well**Comment: [PR - Review of electronic well file indicates last reported production was Dec 2017.](#)

Corrective Action:

Date:

Facility ID: 417633 Type: WELL API Number: 067-09817 Status: PR Insp. Status: PR**Producing Well**Comment: [PR - Review of electronic well file indicates last reported production was Dec 2017.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND, TIMBER

Comment: [Revegetation of interim reclamation area is progressing with established grasses.](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment

Corrective Action

Date _____

Guy line anchors marked? Pass

Comment

Corrective Action

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: COMMERCIAL

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil tanks with spill prevention.
Gravel	Pass					
Rip Rap	Pass					
Compaction	Pass	Gravel	Pass			

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304391	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385116