

Location				
Lease Road:				
	Type Access			
	comment:			
	Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
	Type WELLHEAD			
	Comment:			
	Corrective Action:			Date:
Emergency Contact Number:				
	Comment:	<input type="text" value="ok"/>		
	Corrective Action:	<input type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type WELLHEAD			
	Comment:	<input fence"="" pipe="" type="text" value="1 1/2"/>		
	Corrective Action:			Date:
Equipment:				
Type: Plunger Lift	# 1			corrective date
	Comment:	<input type="text" value="intermitter controller on wellhead"/>		
	Corrective Action:			Date:
Venting:				
Yes/No	NO			
	Comment:			
	Corrective Action:			Date:
Flaring:				
Type	Ignitor/Combustor			
	Comment:			
	Corrective Action:			Date:

Inspected Facilities

Facility ID: 244492 Type: WELL API Number: 123-12287 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
High Risk Inspection	montoyaj	02/16/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401548459	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4380897
677400607	Well Sigh and Battery Prod Equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4380889