

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2018

Submitted Date:

02/19/2018

Document Number:

688301196**FIELD INSPECTION FORM**Loc ID 320702 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLCAddress: 730 17TH ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Barbula, Don	(303) 893-2503	dbarbula@bayswater.us	
Chesson, Bob		robert.chesson@state.co.us	COGCC EPS
Pittman, David	303-204-1481	ddp.com@msn.com	All Inspections
Blyth, Tom	(303) 893-2503	tblyth@bayswater.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204551	WELL	SI	08/01/2015	GW	005-06636	TAMI STATE 1	PA

**General Comment:**PA. Operator contacted Anadarko about their on location riser.

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
Other	Tank	<= 1 bbl		
Comment:	Open top tank for PA operations overtopped on Friday, 2/16/2018 after cement truck cleanout to the tank (see attached photo). Inspector notified onsite rep.			
Corrective Action:	For a spill - "Cleanup and properly treat or dispose in accordance with Rule 907.d.(2)." Contact COGCC EPS.			Date: 02/21/2018

In Containment: No

Comment: Spill area is located near tank battery that will be reclaimed after the PA.

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 204551 Type: WELL API Number: 005-06636 Status: SI Insp. Status: PA

**Cement**Cement Contractor

Contractor Name: \_\_\_\_\_

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): 110

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: 2/14/2018 Cased Hole shot 6 holes @ 6148' and set CICR @ 6098', Ranger pumped 45 sxs below CICR and 5 sxs above CICR of 15.8 ppg cement, Foster Trucking brought fresh water from Wagistic  
 2/15/2018 Cased Hole cut casing at 1190', stage tool at 1037'-1041' per wireline, could not pull pipe  
 2/16/2018 Cased Hole could not get gun through cut, well was circulated, Pioneer wireline got down to 1260' with 6 shots, set CICR at 1140', Ranger pumped 60 sxs of 15.8 ppg cement, 55 below and 5 on top, Foster Trucking brought fresh water  
 Plan to cut casing at 682' on Monday, 2/19/2018 and cement 300 sxs to surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Workover**Comment: Eastern Colorado Well Service Rig #14

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401549240	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381372">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381372</a>
688301211	Bayswater Tami State 1 PA	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381370">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381370</a>