

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2018

Submitted Date:

02/22/2018

Document Number:

674200482**FIELD INSPECTION FORM**
 Loc ID 318321 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------|---------|
| , | | cogcc@kpk.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 241101 | WELL | PR | 07/01/2017 | OW | 123-08889 | CHAMPLIN 86 AMOCO B 4 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|-----------------------------------------|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign not Legible rust on sign see photo | | |
| Corrective Action: | Install sign to comply with Rule 210.e. | Date: | 04/23/2018 |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | Date: _____ |
| Corrective Action: | | |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---------------------------------------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Fabricated metal | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Fabricated Metal for electrical control box | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electrical panels | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electrical | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|----------------------------------|----------|---------------------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| | | | CENTRALIZED BATTERY | | , |
| Comment: | PRODUCES TO BATTERY AT 123-08756 | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|-----------|--|
| Condition | |
|-----------|--|

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|----------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 241101 | Type: | WELL | API Number: | 123-08889 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Intermiten | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| BradenHead | | | | | | | | | |
| Comment: | Appears to be plumbed to surface | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|-----------------------------------------------------------------|--------|------------|
| Sign not replaced from Inspection Doc#678800087 | gomezj | 02/22/2018 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 674200483 | Faded sign at Pump Jack | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4387668 |