

Inspection Photos
Location Name: UPRR 50 PAN AM D-1
API: 05-123-09386



Pumping jack signage looking west



Location site looking NW

Inspection Photos
Location Name: UPRR 50 PAN AM D-1
API: 05-123-09386



Wellhead looking SE