

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/20/2018

Submitted Date:

02/20/2018

Document Number:

679904035

FIELD INSPECTION FORM

Loc ID 321015 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	BACA Inspections
Crane, Rocky	719-529-0682	rockycrane@yahoo.com	Pumper (BACA)

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205785	WELL	PR	08/01/2017	GW	009-06200	ROLLINS RUTHERFORD 1A-20	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
	Type	Access	
	comment:	Two track through pasture	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	OTHER	
	Comment:	Lease sign by meter shed	
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	SEPARATOR	
	Comment:	Pipe fence around VGS	
Corrective Action:			Date:
	Type	PUMP JACK	
	Comment:	Wire fence around unit and wellhead	
Corrective Action:			Date:
	Type	OTHER	
	Comment:	Metal panels around pipeline riser at meter shed	
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
	Comment:	Meter run is 500' west of wellhead	
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
	Comment:	Electric panel, cathodic rectifier, bellows meter (for domestic use)	
Corrective Action:			Date:
Type: Vertical Separator	# 1		
	Comment:	Vertical gas separator north of wellhead by bellows meter (for domestic use)	
Corrective Action:			Date:

Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Parkersburg unit		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		37.333410,-102.406800
Comment:	Fiberglass open top water tank. Tank is empty at time of inspection. Water leg is disconnected and tank is not in use				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 205785 Type: WELL API Number: 009-06200 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Not flowing at time of inspection. Meter run is 500' west of wellhead](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: [Access is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401550970	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4383163