

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/20/2018

Submitted Date:

02/20/2018

Document Number:

679904037

**FIELD INSPECTION FORM**

Loc ID 321131 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10626  
Name of Operator: DOVER ATWOOD CORPORATION  
Address: 1875 HARSH AVENUE SE  
City: MASSILLON State: OH Zip: 44646

**Findings:**

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	<a href="#">BACA Inspections</a>
Crane, Rocky	719-529-0682	rockycrane@yahoo.com	<a href="#">Pumper (BACA)</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206109	WELL	PR	09/13/1993	GW	009-06525	FEDERAL 2-16X	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sticker and stencil on water tank		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Wire panels around unit and wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>					corrective date
Type: Prime Mover	# 1				
Comment:	Electric motor				
Corrective Action:			Date:		
Type: Ancillary equipment	# 2				
Comment:	Electric panel and cathodic rectifier				
Corrective Action:			Date:		
Type: Pump Jack	# 1				
Comment:	Churchill unit				
Corrective Action:			Date:		

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		37.348620,-102.393870

Comment:		Fiberglass water tank. Water leg is disconnected at wellhead. Tank is empty at time of inspection and not in use		
Corrective Action:				Date:
<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 206109 Type: WELL API Number: 009-06525 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Not flowing at time of inspection. Meter run is 2450' SE @ COPE NELLIE 1-16](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: [Access is grassed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401550972	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4383165">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4383165</a>