

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/22/2018

Submitted Date:

02/27/2018

Document Number:

679700812**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10071Name of Operator: BARRETT CORPORATION* BILLAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Jeremy Ferrin		dnr_cogccenforcement@state.co.us	
Inspections, Field		COGCC_FIR@billbarrettcop.com	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448950	LAND APPLICATION SITE				-	SANDY HILL 5-61-29	EI
452946	SPILL OR RELEASE	AC	11/07/2017		-	Sandy Hills Spreadfield	EI
454016	SPILL OR RELEASE	AC	02/09/2018		-	Sandy Hill 5-61-29	EI

General Comment:[Followup to Inspection #679700799](#)

Inspected Facilities								
Facility ID:	448950	Type:	LAND	API Number: -	Status:	Insp. Status:	EI	
Facility ID:	452946	Type:	SPILL OR	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	454016	Type:	SPILL OR	API Number: -	Status:	AC	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: DRILLING FLUIDS

Estimated Spill Volume: _____

Comment: Operator submitted Form 19 Initial/Supplemental Spill Report Doc#401538578 on 2/8/2018. Operator submitted laboratory analytical data via Form 19. Resolution will be handled with further reporting via Form 19 and/or Form 27 as appropriate.

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Land Application	Adequate		
Comment	Drill cuttings piles removed and spread and incorporated. No stockpiles of drill cuttings were observed.			
Corrective Action				Date: _____
Drill Cuttings	Land Application	Adequate		
Comment	Pond of fluids has been removed. No standing drilling fluids observed.			
Corrective Action				Date: _____

Spill/Remediation:

Comment: Operator submitted laboratory analytical data via Form 19. Resolution will be handled with further reporting via Form 19 and/or Form 27 as appropriate.

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
679700814	SandyHill Inspection Photos 2-22-2018	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388211