

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2018

Submitted Date:

02/28/2018

Document Number:

685304396**FIELD INSPECTION FORM**Loc ID 334213 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:27 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215251	WELL	PR	09/11/1990	GW	067-06856	GARY BEEBE B 1	PR
292929	WELL	PR	10/15/2007	GW	067-09413	GARY BEEBE B 3	PR

General Comment:[Inspection completed as routine inspection requirement.](#)[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)[See link at end of report for path to downloadable pictures.](#)

Location				
Lease Road:				
Type	Access			
comment:	Dirt and gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Framed metal sign at location entrance.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Stand alone sign at produced water tank.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Operator contact information posted on wellhead sign.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Stock panel fencing.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Stock panel fencing. Includes gas meter run.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Riser on S perimeter. Steel post and pole barrier.			
Corrective Action:				Date:
Equipment:				
Type: Flow Line	# 2			corrective date
Comment:	B#3 In use - 3" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 3" steel line from separator outlet to gas meter inlet. All points co-located.			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Electrical supply equipment.			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator.		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Water can and valve set.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Pipeline.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pipeline telemetry equipment.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	B#1 In use - 3" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 3" steel line from separator outlet to gas meter inlet. All points are co-located.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Riser.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Cathodic protection equipment.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:	Single building with 2 separator systems.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:	Partially buried steel tank with metal containment ring.				

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 95 BBLS						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 215251 Type: WELL API Number: 067-06856 Status: PR Insp. Status: PR**Producing Well**Comment: [PR - Review of electronic well file indicates last reported production was Dec 2017.](#)

Corrective Action:

Date:

Facility ID: 292929 Type: WELL API Number: 067-09413 Status: PR Insp. Status: PR**Producing Well**Comment: [PR - Review of electronic well file indicates last reported production was Dec 2017.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Location partially snow covered at time of inspection. Revegetation is progressing with established grasses.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			
		Gravel	Pass			

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304416	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388725