

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2018

Submitted Date:

02/28/2018

Document Number:

685304412**FIELD INSPECTION FORM**Loc ID 333934 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 600 E EXCHANGE AVECity: FORTH WORTH State: TX Zip: 76164**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beaty, Brent	505-330-3210	brent_beaty@xtoenergy.com	SW Inspection Reports
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	SW Inspection Reports
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258202	WELL	PR	11/01/2017	GW	067-08335	SQUIRES 2	PR
301405	WELL	PR	11/16/2009	GW	067-09702	SQUIRES 3	PR

General Comment:[Inspection completed as routine follow up inspection.](#)[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)[See link at end of report for path to downloadable pictures.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	There is pipe, regulators, and fittings just off the NE corner of location. Removed corrective action completed.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained soil at the muffler, ground behind lube oil tank, and supply gas knock out for the Squires 3. Clean up corrective action completed.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained soil at the back of the Squires 2 pump jack. Less than a 5 gallon bucket clean up. Corrected by comment.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>258202</u>	Type:	<u>WELL</u>	API Number:	<u>067-08335</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>301405</u>	Type:	<u>WELL</u>	API Number:	<u>067-09702</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil tank on spill prevention.
Rip Rap	Pass					
Gravel	Pass	Gravel	Pass			
Waddles	Pass					

Comment: [Lube oil tank for the Squires 3 has no spill prevention. Tank removed corrective action completed.](#)

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304448	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4389794