

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2018

Submitted Date:

02/22/2018

Document Number:

677400635**FIELD INSPECTION FORM**

Loc ID 336189 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Precup, Jim		james.precup@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245691	WELL	SI	11/07/2014	OW	123-13486	FREEMAN 13-2	SI

General Comment:

Location			
Lease Road:			
Type	Main		
comment:			
Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	no emergency contact number on wellhead		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	03/22/2018
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	ok		
Corrective Action:		Date:	
Good Housekeeping:			
Type	WEEDS		
Comment:	weeds around tank battery, prod water tank, and by seperator		
Corrective Action:	Comply with Rule 603.f .	Date:	03/05/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	Tank	>= 5 bbls	
Comment:	soiled dirt on back of prod tank drain lines, inside seperator house, and 3" pipe on seperator leaking		
Corrective Action:	"Contact COGCC EPS staff regarding Rule 906.c."		Date: 02/24/2018
In Containment: Yes			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		

Comment: concrete barriers around wellhead			
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.079150,-104.508420
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		40.079140,-104.508610
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	245691	Type:	WELL	API Number:	123-13486	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									
BradenHead									
Comment: OK									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Inspection of location we inherited from Tudex Freeman 13-2	montoyaj	02/22/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401553358	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385336
677400636	BATTERY SIGN STAINED SOIL BEHIND PROD TANK	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385325
677400637	STAINED SOIL DRAIN AND LOAD LINE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385326
677400638	SOILED DIRT AND WEEDS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385327
677400639	STAINED SOIL AND LEAKING 3" PIPE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385328
677400640	STAINED SOIL SEPERATOR HOUSE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385329
677400641	WEEDS AND 3" RISER	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385330
677400642	LOOKING TO SE FROM NW FREEMAN 13-2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385331
677400643	LOOKING TO NW FROM SE SIDE OF LOCATION	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385332