

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2018

Submitted Date:

02/23/2018

Document Number:

679700811**FIELD INSPECTION FORM**

Loc ID 440823 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Bonanza Inspections		EHSRC@bonanzacrk.com	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440823	LOCATION	AC	02/09/2015		-	State Antelope CPF O-1 Pad	EI
454117	SPILL OR RELEASE	AC			-	SA CPF O-1 Waterleg	EI

General Comment:

Inspected Facilities									
Facility ID:	440823	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	454117	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: COGCC Environmental inspection of release from 3" diameter water line entering State Antelope T-1 pad from pad to east. Bonanza personnel indicated that release occurred at 90 elbow from internal corrosion or erosion (root cause is pending). Small excavation present at release point. Initial soil sample results are pending. Operator will provide root cause and corrective action along with confirmation soil sample results via Form 19 Supplemental Report. Photo attached.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401553944	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385679
679700813	Excavation showing failure point at elbow	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4385677