

Inspected Facilities

Facility ID: 453622 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC met Extraction personnel onsite to view area affected by the fire and spill of 12/22/2017 and to discuss and witness soil sampling. Extraction indicated that investigators for several parties retain control of the site, which prohibits access to removal of impacted pad material. Extraction will submit results of today's soil samples via Form 19 Supplemental Report and include an estimated timeframe for cleanup. Photos of soil sample locations attached.

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700816	Stromberger Sample Location Photos 3-2-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4392149