

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2018

Submitted Date:

02/25/2018

Document Number:

688301225**FIELD INSPECTION FORM**Loc ID 320702 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLCAddress: 730 17TH ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Barbula, Don	(303) 893-2503	dbarbula@bayswater.us	
Pittman, David		ddp.com@msn.com	
Blyth, Tom	(303) 893-2503	tblyth@bayswater.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204551	WELL	SI	08/01/2015	GW	005-06636	TAMI STATE 1	PA

General Comment:Cut, Cap and Cover PA Inspection

Inspected Facilities

Facility ID: 204551 Type: WELL API Number: 005-06636 Status: SI Insp. Status: PA

CementCement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: 2/19/2018 600 sxs from 690', tagged at 16' BGS on 2/20/2018 by opearator
2/21/2018 5 sxs to surface of cut casing, ~6' BGS. Flowline riser at wellhead still in place
(see attached photo).

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401554595	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4386275
688301250	Bayswater Tami State 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4386262