

Inspection Photos

02/26/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312292

Inspection Doc. Number: 682503171
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 1: Photo of sign at the well.



Photo 2: Photo taken from the central area of the location, facing east. Photo shows areas of erosion degradation. Erosion has not been repaired or stabilized and no BMPs have been installed or maintained per corrective actions.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 3: Photo taken from the central area of the location, facing east. Photo shows areas of erosion degradation. Erosion has not been repaired or stabilized and no BMPs have been installed or maintained per corrective actions.



Photo 4: Photo taken from the south end of the location, facing west. Photo shows erosion degradation has not been repaired or stabilized, no BMPs have been installed or maintained, and no remediation and/or reclamation activities have been conducted per corrective actions.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 5: Photo taken from the south end of the location, facing east. See comments under photo 4. Six foot measuring stick for reference.



Photo 6: Photo taken from the south end of the location, facing east. See comments under photo 4. Six foot measuring stick for reference.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 7: Photo taken from the south end of the location, facing southwest. See comments under photo 4. Six foot measuring stick for reference.



Photo 8: Photo taken from the south end of the location, facing north. See comments under photo 4.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 9: Photo taken from the southeast end of the produced water pit, facing west. Photo shows areas of erosion degradation on the adjacent lands due to runoff and salt kill. Photo shows no remediation activities appear to have been conducted, and no stabilization and stormwater BMPs have been installed or maintained per corrective actions.




Photo 10: Photo taken from the southeast end of the produced water pit, facing south. See comments under photo 9.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 11: Photo taken from the southwest end of the produced water pit, facing north. See comments under photo 9.



Photo 12: Photo taken from the southwest end of the produced water pit, facing west. See comments under photo 9.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 13: Photo taken from the east end of the pit, facing northwest. Photo shows tinhorn has not been removed.



Photo 14: Photo taken from the east end of the produced water pit, facing west. Photo shows erosion degradation has not been repaired or stabilized, no BMPs have been installed or maintained, and no remediation and/or reclamation activities have been conducted per corrective actions.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 15: Photo taken from the east end of the produced water pit, facing west. See comments under photo 14. 6 foot measuring stick for reference.



Photo 16: Photo taken from the east end of the produced water pit, facing west. See comments under photo 14. 6 foot measuring stick for reference.