

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2018

Submitted Date:

02/27/2018

Document Number:

679700812**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10071Name of Operator: BARRETT CORPORATION\* BILLAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Jeremy Ferrin		dnr_cogccenforcement@state.co.us	
Inspections, Field		COGCC_FIR@billbarrettcop.com	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448950	LAND APPLICATION SITE				-	SANDY HILL 5-61-29	EI
452946	SPILL OR RELEASE	AC	11/07/2017		-	Sandy Hills Spreadfield	EI
454016	SPILL OR RELEASE	AC	02/09/2018		-	Sandy Hill 5-61-29	EI

**General Comment:**[Followup to Inspection #679700799](#)

Inspected Facilities									
Facility ID:	448950	Type:	LAND	API Number:	-	Status:		Insp. Status:	EI
Facility ID:	452946	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	454016	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Environmental****Spills/Releases:**

Type of Spill: DRILLING FLUIDS

Estimated Spill Volume: \_\_\_\_\_

Comment: Operator submitted Form 19 Initial/Supplemental Spill Report Doc#401538578 on 2/8/2018. Operator submitted laboratory analytical data via Form 19. Resolution will be handled with further reporting via Form 19 and/or Form 27 as appropriate.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Land Application	Adequate		
Comment	Drill cuttings piles removed and spread and incorporated. No stockpiles of drill cuttings were observed.			
Corrective Action				Date: _____
Drill Cuttings	Land Application	Adequate		
Comment	Pond of fluids has been removed. No standing drilling fluids observed.			
Corrective Action				Date: _____

**Spill/Remediation:**

Comment: Operator submitted laboratory analytical data via Form 19. Resolution will be handled with further reporting via Form 19 and/or Form 27 as appropriate.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401557677	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388252">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388252</a>
679700814	SandyHill Inspection Photos 2-22-2018	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4388211</a>