

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2018

Submitted Date:

02/27/2018

Document Number:

682600448**FIELD INSPECTION FORM**

Loc ID _____	Inspector Name: _____ Kosola, Jason	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>61250</u> Name of Operator: <u>MULL DRILLING COMPANY INC</u> Address: <u>1700 N WATERFRONT PKWY B#1200</u> City: <u>WICHITA</u> State: <u>KS</u> Zip: <u>67206-</u>				<b>Findings:</b> <u>3</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Smalley, Carl	(719) 767-8805	csmalley@mulldrilling.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454138	SPILL OR RELEASE	AC	02/26/2018		-	Mull Unit Sorrento Field 2	EI

**General Comment:**

This is an environmental inspection to document status of spill of produced water. Any corrective actions from previous inspections that have not been addressed are still applicable.

Spill 454138 was reported by operator on 2/23/2018 (COGCC Doc #401554778). Operator reported an approximate 3bbl spill of crude oil from pipeline from wellhead to tank battery. Inspection of spill location confirms an approximate 3bbl crude oil release from pipeline (see attached photos). Operator had stopped leak and was in the process of repairing damaged pipeline at the time of inspection.

Mull Drilling personnel on site estimated that at the time of spill the well feeding the pipeline was making 80% produced water and 20% oil.

Inspected Facilities									
Facility ID:	454138	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 3

Comment: Operator reported spill of crude oil from pipeline.

Corrective Action: Operator shall provide root cause of spill and prevention procedures on Form 19 Subsequent within 10 days of spill as required per Rule 906.b

Date: 03/04/2018

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water:

Depth to Ground Water:

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Confirmation soils samples from spill area shall be obtained to determine compliance with COGCC Table 910-1 constituents prior to requesting closure of spill or remediation. All affected soils must be remediated or removed and disposed of at an approved facility. Soil samples from spill location and background location should be submitted to COGCC area Environmental Protection Specialist. If soils are to be remediated in situ then operator shall submit Form 27 Remediation Plan.	kosolaj	02/27/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401556494	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4387891">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4387891</a>
682600449	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4387890">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4387890</a>